

APPENDIX C

Abstract

A method of determining machining instructions during machining of a workpiece using a machine having a cutter, the surfaces of the workpiece being defined by a plurality of programmed instructions obtained by trigonometric analysis of the required curvatures of the surfaces.